Guam Waterworks Authority (GWA) Sanitary Survey Summary Table

Assest Evaluation Sanitary Survey							
Asset Name	Date Visited	Form Included In Report	NEIC DW Photolog	<u>Pictures</u>			
ASSEC NAME	Date Visited	Tom meladed in Report	Ugum Intake, Ugum	<u>r ictures</u>			
			Water Treatment				
Ugum Water Treatment Plant	4/25/2012	Sanitary Survey Inventory	Plant	1-60			
ogani water rreatment rant	4/23/2012	Sanitary Survey inventory	Ugum Water	1 00			
Ugum Water Treatment Plant	4/26/2012	Sanitary Survey Inventory	Treatment Plant	61-73			
Brigade Pump Station	4/26/2012	Pump Station	Southern	74-82			
Windward Hills Tank	4/26/2012	Storage	Southern	83-86			
Windward Hills Pump Station	4/26/2012	Pump Station	Southern	87-95			
Sinifa Tank	4/26/2012	Storage	Southern	96-100			
Santa Rita Springs	4/26/2012	Springs and Infiltration Galleries	Central	101-109			
Y15 Well	4/27/2012	Well Head and Chlorination Facility	Northern	110-120			
Santa Rosa Tank	4/27/2012	Storage	Northern	121-127			
Santa Rosa Pump Station	4/27/2012	Pump Station	Northern	128-132			
Gayinero Pump Station	4/27/2012	Pump Station	Northern	133-138			
Y-9 Well	4/27/2012	Well Head and Chlorination Facility	Northern	139-146			
Yigo #1 Tank	4/27/2012	Storage	Northern	147-149			
Yigo #2 Tank	4/27/2012	Storage	Northern	150-151			
Yigo Elevated Tank	4/27/2012	Storage	Northern	152-154			
Barriagada #3 Tank	4/27/2012	Storage	Northern	155-160			
Hyundai Pump Station	4/27/2012	Pump Station	Northern	161-163			
A31 Well	4/30/2012	Well Head and Chlorination Facility	Northern	164-168			
Underground Injection Control (UIC) Ponding Basin	4/30/2012	None	Northern	169-170			
Manhole Upstream Of UIC	4/20/2012	Nama	Ni a utla a uu	474			
Ponding Basin	4/30/2012	None	Northern	171			
Manhole on Route 4	4/30/2012	None	Northern	172			
A23 Well	4/30/2012	Well Head and Chlorination Facility	Northern	173-175			
A25 Well A6 Well	4/30/2012 4/30/2012	Well Head and Chlorination Facility Well Head and Chlorination Facility	Northern Northern	176-178 179			
Chaot Wastewater Pump	4/30/2012	Well Head and Chlorillation Facility	Northern	179			
Station	4/30/2012	None	None	None			
A1 Well	4/30/2012	Well Head and Chlorination Facility	Northern	180-183			
A3 Well	4/30/2012	Well Head and Chlorination Facility	Northern	184			
Dairy Wastewater Pump	4/30/2012	vven rieda dila emormation i denity	Northern	104			
Station	4/30/2012	None	None	None			
A9 Well	4/30/2012	Well Head and Chlorination Facility	Northern	185-186			
A10 Well	4/30/2012	None - Not In Operation	Northern	187			
Mangilao Wastewater Pump	., 50, 2012	Not in operation		107			
Station	4/30/2012	None	None	None			
A21 Well	4/30/2012	Well Head and Chlorination Facility	Northern	188-189			
D5 Well	5/1/2012	Well Head (No Disinfection)	Northern	190-192			
EX5 Well	5/1/2012	Well Head and Chlorination Facility	Northern	193			
D14 Well	5/1/2012	Well Head and Chlorination Facility	Northern	None			
D7 Well	5/1/2012	Well Head and Chlorination Facility	Northern	194			

Guam Waterworks Authority (GWA) Sanitary Survey Summary Table

		Assest Evaluation Sanitary Survey		_
Asset Name	Date Visited	Form Included In Report	NEIC DW Photolog	<u>Pictures</u>
F13 Well	5/1/2012	Well Head and Chlorination Facility	Northern	195
F15 Well	5/1/2012	Well Head and Chlorination Facility	Northern	None
F18 Well	5/1/2012	Well Head and Chlorination Facility	Northern	None
F8 Well	5/1/2012	Well Head and Chlorination Facility	Northern	196
Manchanao Wastewater				
Pump Station	5/1/2012	None	None	None
F5 Well	5/1/2012	Well Head and Chlorination Facility	Northern	197
Astumbo Wastewater Pump				
Station	5/1/2012	None	None	None
Astumbo Ponding Basin	5/1/2012	None	None	None
F3 Well	5/1/2012	Well Head and Chlorination Facility	Northern	198-200
Y10 Well	5/1/2012	Well Head and Chlorination Facility	Northern	201-206
Ypaopao Wastewater Pump				
Station	5/1/2012	None	Northern	202, 205
Ypaopao Ponding Basin	5/1/2012	None	Northern	205-206
Navy Water Treatment Plant	5/2/2012	None	Northern	None
Santa Rita Tank	5/2/2012	Storage	Central	207-211
Distribution System Pipe				
Repair	5/2/2012	None	Central	212-216
Agat # 1 Tank	5/2/2012	Storage	Southern	None
Agat # 1 Pump Station	5/2/2012	Pump Station	Southern	217
AWR Sampling Station	5/2/2012	None	Southern	None
Umatac Tank	5/2/2012	Storage	Southern	218-219
Umatac # 2 Pump Station	5/2/2012	Pump Station	Southern	220
Pigua Tank	5/2/2012	Storage	Southern	221-222
Pigua Pump Station	5/2/2012	Pump Station	Southern	223
Geus Pump Station	5/2/2012	Pump Station	Southern	224-233
Airport Water Treatment			Airport Water	
Plant	5/3/2012	Sanitary Survey Inventory	Treatment System	234-243